

Oil Field Environmental Incident Summary

Incident: 20140807174300

Date/Time of Notice: 08/07/2014 17:43

Responsible Party: SM ENERGY COMPANY

Well Operator: SM ENERGY COMPANY

Well Name: USA 43-11

Field Name: CARTWRIGHT

Well File #: 90002

Date Incident: 8/5/2014

Time Incident: 11:00

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 104

Sec: 11

Qtr: SE NE

Location Description:

Submitted By: Luke Studer

Received By:

Contact Person: Luke Studer

PO BOX 7168

BILLINGS, MT 59103-7168

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1.5 Mile

Distance Nearest Water Well: 1.5 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	2	Barrels			0	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/9/2015

Clean Up Concluded: 8/6/2014

Risk Evaluation:

None

Areal Extent:

NA

Potential Environmental Impacts:

None

Action Taken or Planned:

Shut in SWD and Isolated leaking pipe.

Wastes Disposal Location: Contaminated soil will be hauled to an approved disposal.

Agencies Involved:

Updates

Date: 8/13/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location pipeline leak, remained on location within the diking according to the report. NDIC retains oversight.